

S-28-26

32513

VAN

Gravity Inspection	Address			
**Material: Cement	8300 SE Lowry Ave	Yes	No	N/A
Septic Tank	Functioning as intended	✓		
	Level within operating levels	✓		
	All required baffles in place	✓		
	Filter cleaned	N/A		
	Scum 1 st compartment inches	3"		
	Sludge 1 st compartment inches	4"		
	Scum 2 nd compartment inches	N/A		
	Sludge 2 nd compartment inches	✓		
	Pumping needed		✓	
Pump Tank	Functioning as Intended	N/A		
	Scum inches			
	Sludge inches			
	Pumping needed			
Effluent Pump	Appears to be functioning as intended			
	Controls functioning			
	Pump Vault Filter cleaned (N/A = not present)			
	One minute draw down (inches)			
Alarms	Functioning as intended	✓		
Drain Field	Functioning as intended	✓		
	Ponding present		✓	
D-Box	Condition good	N/A		
	Flows adjusted	✓		
General	Components accessible, secure, good condition	✓		
	Surfacing effluent or sewage		✓	
	Water tight, no visual leaks		✓	
	Improper encroachment onto components		✓	
	Component settling		✓	
	Abnormal ponding		✓	
	Components adequately covered	✓		
	Site maintenance required	✓		

Follow Up Needed? Yes (No)

Notes:

roots in tank but not causing issues at this
Time. suggest root-X to clear roots

Inspected by: